


RAP Flow Diagram



Features

- Flash Drying
- Optional Cooling
- Lime Addition As Spray (SO₂ Control)
- Full Recycle (Required)
- Optional - Stabilization Lime Addition
- Optional - SO₃/Acid Addition (EI Hg Control)